General Environmental Incident Summary

Incident: 5450 *Notice:* 7/5/2017 0700 *Occurred:* 7/5/2017 0400

DEM Incident No: No Further Action: ✓

Responsible Party: CHS Transportation

County: Burleigh
Twp Rng Sec Qtr: 138 80 4

Lat Long + Method: 46.79533 -100.79430 Interpolation from map

Location Description: Red Carpet Gas Station 919 S Washington St. Bismarck ND

Submitted By Info: Eric Pearson

Cenex Harvest States 4115 27th Ave N

Grand Forks ND 58203

Received By Info:

Contact Info:

4115 27th Ave N

Grand Forks ND 58203

Affected Medium: 03 - soil
Near. Occupied Bldg: 35 Feet

Type of Incident: Tank Overflow

Release Contained: Yes
Reported to NRC: Unknown
Contaminant: Clear Diesel
Volume of Release: 15 gallons

Duration of Release: 1 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: Number of Injuries: Cause of Incident:

Station tank reader was off and fuel being delivered overflowed the tank.

Risk Evaluation:

None

Potential Env. Impacts:

Very minimal (if any) as the spill was on concrete and was contained in a short time frame.

Action Taken/Planned:

Spill was contained by the Bismarck Fire Dept with Floor dry and spill mats. We have Keitu Eng. onsite cleaning up the contained fuel and floor dry materials.

Wastes Disposal Location:

More than likely through Clean Harbors

Other Agencies Involved:

Local Fire Department

Updates

Date: 7/5/2017 Status: Reviewed - Follow-up Required

Author: Crowdus, Kory

Notes:

Release at gas station. Follow-up is required.

Updated Volume: None at the time of this update

Date: 7/17/2017 Status: Inspection

Author: Schmitt, Bryan

Notes:

Time: 12:30 PM CST, Temp: 88 F

Spill occurred on concrete within the Red Carpet Gas Station property. There was no visual sign of diesel or impacts to nearby vegetation. The spill was contained within the property curb and on concrete. Employee of Red Carpet Gas Station commented that a small portion of diesel may have migrated to a storm catch basin on the property. No visual sign of impact was seen around or within the storm catch basin.

Updated Volume: None at the time of this update